

VACUUM PUMP RESTORED WITH BELZONA

ID: 3332

Industry: General Industry

Customer Location: Sheet metal factory, Casablanca,
Morocco

Application: FBC-Fans, Blowers and Compressors


Application Date: November 2011

Substrate: Steel

Products: * Belzona® 1321 (Ceramic S-Metal) ,
* Belzona® 1111 (Super Metal) ,

Problem

Corrosive fumes had caused severe corrosion on all parts of this vacuum pump.



Photograph Descriptions

- * Original stator and end covers ,
- * Original rotor ,
- * Completed application on the stator ,
- * Completed application on the rotor ,

Application Situation

Liquid ring vacuum pump used in metal processing

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FBC-2, FBC-5 and FBC-10.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

The Belzona has restored efficiency of the pump and will protect from future corrosion for many years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2025