

# FÖRDERBAND-REPARATUR MIT BELZONA

ID: 3361

Industrie: Leistung  
Anwendung: Maschinen zur Handhabung von Feststoffen  
Substrat: Gummi  
Produkte: \* Belzona 2311 (SR Elastomer),

Standort des Kunden: Kraftwerk, Bulgarien  
Antragsdatum: August 2002

## Problem

Durch einen mechanischen Schaden am Bandabstreicher wurde die Metallverstärkung freigelegt.



## Fotobeschreibungen

- \* 1. Ansicht der Förderanlage ,
- \* 2. Grundierung mit Belzona 2911 (Elastomer QD Conditioner) ,
- \* 3. Reparatur mit Belzona 2311 (SR Elastomer) ,

## Anwendungssituation

5 km langes Förderband für den Transport von Kohle zum Kraftwerk.

## Anwendungsverfahren

Die Anwendung wurde gemäß dem Belzona Know-how System Infoblatt SHM-1 durchgeführt.

## Belzona-Fakten

Für den Kunden war bei der Reparatur vor allem eine möglichst kurze Ausfallzeit entscheidend. Belzona wurde aufgrund seiner im Gegensatz zur Vulkanisation effektiven, einfachen und schnellen Anwendung ohne Spezialwerkzeuge gewählt.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

