# 600 M2 FLAT ROOF WATERPROOFED WITH BELZONA

ID: 3441

Industry: Sugar Customer Location: Wastewater treatment plant,

Rosenheim, Germany

Application: RPA-Roof Problem Areas

Substrate: Roofing felt, steel

Products: \* Belzona® 3111 (Flexible Membrane),

#### Problem

Melt water had regularly leaked through the roof into the hall below as a result of the snow-prone winters in this region.







Application Date: August 2010



## **Photograph Descriptions**

- \* Damaged roofing substrate,
- \* Application to detailed areas,
- \* Application in progress,
- \* Completed application,

### **Application Situation**

Leaking 600 m2 flat roof

## **Application Method**

Application carried out in accordance with Belzona Know-How System Leaflets RPA-1, 6, 7 & 8.

#### **Belzona Facts**

The application took only 3 days to complete. Despite the harsh and snowy winter of 2010/2011, the roof is still completely watertight today and the customer is very satisfied with the result. In contrast to commonly used weatherproofing materials, the cold applied, microporous Belzona system allowed for seamless encapsulation of the roof, adapting to the complex, irregular roof contours as well as roof movements.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve