

BELZONA TANK FARM

ID: 36


Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas

Customer Location: Chemical Plant in South Alabama, USA
Application Date: August 1995

Substrate: Concrete and Polymeric Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4311 (Magma CR-1) ,

Problem

Harsh chemicals attacking existing substrate which was installed in 1993.



Photograph Descriptions

- * View of damage to polymeric repair compound ,
- * Application of Belzona® 4311 (Magma CR-1) in progress ,
- * 5000 sq. ft. area protected ,

Application Situation

Chemical containment area (5000 sq. ft.)

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets TCC-9 and TCC-15.

Belzona Facts

The previous polymeric concrete repair material was damaged by chemical attack. The concrete was repaired and all areas protected.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve