

# CLASSIC BELZONA PUMP REFURBISHMENT-OUTPUT INCREASES 9.5% AFTER 3½ YEARS

ID: 363

Industry: Water / Wastewater

Customer Location: National water supply company in Tunisia

Application: CEP-Centrifugal Pumps

Application Date: September 2002

Substrate: Cast Iron

Products: \* Belzona® 1111 (Super Metal) Belzona® 1341 (Supermetalglide) ,

## Problem

Output from the pumps was drastically reduced from the new condition due to corrosion and cavitation damage.



## Photograph Descriptions

\* Damaged pump Neck ring seats restored to original sizes Complete repair Coating in good condition after 3-1/2 years of service ,

## Application Situation

Two badly corroded/cavitated centrifugal KSB water supply pumps.

## Application Method

Application was carried out in accordance with Belzona System Leaflets CEP-2 and CEP-10.

## Belzona Facts

Flow rate of New Pump - 540 L/sec (142 gal/sec) Flow rate of damaged pump - 480 L/sec (126 gal/sec) Flow rate of repaired pump - 540 L/sec (142 gal/sec), an increase of more than 12% over the corroded pump. After 3-1/2 years, the flow rate of the repaired pump is 530 L/sec (140 gal/sec), an increase of more than 9.5% over the corroded pump.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
 Repair • Protect • Improve