

BELZONA GRIP SYSTEM MAINTAINS BRAKE TEST EQUIPMENT

ID: 3644

Industry: General Industry

Application: SHM-Solids Handling Machinery

Substrate: Steel

Products: * Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Truck test centre, central Sweden

Application Date: February 2012 (it has been done regularly since 2002)

Problem

The drive rollers in the brake tester lose their grip and do not have sufficient friction with the tyre to complete an accurate test.



Photograph Descriptions

- * Worn rollers in the truck tester ,
- * Close-up of the worn roller ,
- * Roller coated with Grip system of Belzona® 1321 and Silicon carbide aggregate, in the workshop ,
- * Finished application ,

Application Situation

Equipment for testing brake efficiency on trucks.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-12.

Belzona Facts

The customer is happy about the result and the lifetime, which is approximately 4 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

