

BELZONA PREVENTS GALVANIC AND CREVICE CORROSION ON RUDDER HORN

ID: 367

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Oil shipping company*
Application Date: *1988*

Substrate: *Carbon Steel and Bronze*
Products: ** Belzona® 1321 (Ceramic S-Metal) ,*
** Belzona® 1211 (E-Metal) ,*

Problem

Corrosion to internal of rudder horn had allowed the press fitted bronze bearing to become free. Bearing was approximately 908-mm (36-inch) diameter and 1050-mm (41-inch) long.



Photograph Descriptions

- * Belzona materials and team prepared for application. ,
- * Internal shot of bearing. Note arrows for injection ports. ,
- * Bearing after injection and prior to cleaning up of the Belzona® 1211 seal. ,

Application Situation

Corrosion to internal of rudder horn of 280,000 Ton VLCC (Very Large Crude Carrier) required re-fixing of bearing.

Application Method

The bearing was aligned and its position in the housing fixed using alignment bolts. The top and bottom of the housing were sealed using Belzona® 1211, then Belzona® 1321 was injected from below.

Belzona Facts

This method is used both in new-build and repair, and this example illustrates the ability to undertake this work while the vessel is afloat. Use of Belzona materials isolates and permanently fixes the bearing into position preventing galvanic and crevice corrosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve