

BELZONA TACKLES 98% SULFURIC ACID TANK

ID: 376

Industry: *Power*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: ** Belzona® 1111 (Super Metal) ,*
** Belzona® 4311 (Magma CR-1) ,*

Customer Location: *Power Plant in Alabama - U.S.A.*
Application Date: *February 2003*

Problem

Tank coating had failed, leading to severe pitting.



Photograph Descriptions

- * 1. & 2. Before ,
- * 3. & 4. After ,

Application Situation

98% Sulfuric acid tank interior.

Application Method

The application was carried out in accordance with Belzona Know-How Systems leaflet TCC-5. After the tank was neutralized, it was blasted to a near white metal finish.

Belzona Facts

Application saved tens of thousands of dollars in downtime, as disassembly of machine takes four days. Four Months in service - PERFECT!

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve