

# BELZONA REPAIRS AND PROTECTS AUTO REPAIR SHOP FLOOR

ID: 377

Industry: *General Industry*

Customer Location: *Auto Repair Center in Northern Florida - U.S.A.*

Application: *FPA-Floor Problem Areas*

Application Date: *May 2003*

Substrate: *Concrete*

Products: *\* Belzona® 4131 (Magma-Screed) ,  
\* Belzona® 5811 (Immersion Grade) ,*

## Problem

*Floor area damaged due to exposure to sulfuric acid.*



## Photograph Descriptions

- \* Prior to application ,
- \* Prepared floor ,
- \* Belzona® 4131 (Magma-Screed) and Belzona® 5811 (Immersion-Grade) applied to protect application area long term ,

## Application Situation

Parts & Battery Storage Area

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and TCC-15.

## Belzona Facts

The facility is over 30 years old and the customer had made several attempts to repair the floor. In each case, they used some type of concrete repair products to make the repair and coat with several types of paint. Each method was more expensive than the Belzona repair and none were effective.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve