

# BELZONA REPAIRS AND PROTECTS AUTO REPAIR SHOP FLOOR

ID: 377

Industry: General Industry

Customer Location: Auto Repair Center in Northern Florida - U.S.A.

Application: FPA-Floor Problem Areas

Application Date: May 2003

Substrate: Concrete

Products: \* Belzona® 4131 (Magma-Screed) ,  
\* Belzona® 5811 (Immersion Grade) ,

## Problem

Floor area damaged due to exposure to sulfuric acid.



## Photograph Descriptions

- \* Prior to application ,
- \* Prepared floor ,
- \* Belzona® 4131 (Magma-Screed) and Belzona® 5811 (Immersion-Grade) applied to protect application area long term ,

## Application Situation

Parts & Battery Storage Area

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and TCC-15.

## Belzona Facts

The facility is over 30 years old and the customer had made several attempts to repair the floor. In each case, they used some type of concrete repair products to make the repair and coat with several types of paint. Each method was more expensive than the Belzona repair and none were effective.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve