

BELZONA 4000 SERIES FLOOR COATING FOR A STERILIZING ROOM

ID: 378

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4151 (Magma-Quartz Resins) ,

Customer Location: Medical Sanitizers - Minnesota U.S.A.
Application Date: March 2002

Problem

Floor was spalled, cracked and and therefore non-compliant with sanitary requirements.



Photograph Descriptions

- * Final steps of surface preparation ,
- * In progress ,
- * Job complete ,

Application Situation

Floor in a sanitizer room - 100° F at 80% humidity.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3. Shot-blasted floor, followed by thorough cleaning. Roller/brush application of product in a slurry-grade.

Belzona Facts

This customer had put the repair out for bid. The Belzona Solution was over seven times more expensive than the other bids received. Because of the aggressive environment and heavy fork lift traffic, only the Belzona System provided the protection required. Tenacity and great care taken in understanding and appreciating the customer's problem led them to believe in the Belzona Solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve