# BELZONA 4000 SERIES FLOOR COATING FOR A STERILIZING ROOM

ID: 378

Industry: General Industry Customer Location: Medical Sanitizers - Minnesota U.S.A.

Application: FPA-Floor Problem Areas Application Date: March 2002

Substrate: Concrete

Products: \* Belzona® 4151 (Magma-Quartz Resins),

### Problem

Floor was spalled, cracked and and therefore non-compliant with sanitary requirements.







# **Photograph Descriptions**

- \* Final steps of surface preparation ,
- \* In progress ,
- \* Job complete,

### **Application Situation**

Floor in a sanitizer room - 100º F at 80% humidity.

# **Application Method**

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3. Shot-blasted floor, followed by thorough cleaning. Roller/brush application of product in a slurry-grade.

### **Belzona Facts**

This customer had put the repair out for bid. The Belzona Solution was over seven times more expensive than the other bids received. Because of the aggressive environment and heavy fork lift traffic, only the Belzona System provided the protection required. Tenacity and great care taken in understanding and appreciating the customer's problem led them to believe in the Belzona Solution.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve