

BELZONA PROTECTION TO BUTANE TANK BASE

ID: 379

Industry: Chemical & Petrochemical

Customer Location: International Petroleum Company -
Australia

Application: GSS-Gaskets, Seals and Shims

Application Date: 2002

Substrate: Steel, Concrete and Timber

Products: * Belzona® 3211 (Lagseal),

Problem

Corrosion at base of tank. At same time, timber supports were being renewed.



Photograph Descriptions

- * General view of the tank ,
- * Preparation of tank and base underway. Tank jacked up ready to install new timbers ,
- * Application underway ,
- * Application being completed ,

Application Situation

Insulated tank containing Butane at -6°C (21°F).

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

Belzona Facts

Belzona application creates a flexible, waterproof but microporous seal at junction of tank and base to provide long-term corrosion protection.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve