

# BELZONA PROTECTION TO BUTANE TANK BASE

ID: 379

Industry: Chemical & Petrochemical

Customer Location: International Petroleum Company -  
Australia

Application: GSS-Gaskets, Seals and Shims

Application Date: 2002

Substrate: Steel, Concrete and Timber

Products: \* Belzona® 3211 (Lagseal),

## Problem

Corrosion at base of tank. At same time, timber supports were being renewed.



## Photograph Descriptions

- \* General view of the tank ,
- \* Preparation of tank and base underway. Tank jacked up ready to install new timbers ,
- \* Application underway ,
- \* Application being completed ,

## Application Situation

Insulated tank containing Butane at -6°C (21°F).

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

## Belzona Facts

Belzona application creates a flexible, waterproof but microporous seal at junction of tank and base to provide long-term corrosion protection.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve