BELZONA PROTECTS OPEN DRAINS TANK

ID: 385

Industry: Oil & Gas

Application: TCC-Tanks and Chemical Containment

Areas

Substrate: Mild Steel

Products: * Belzona® 1521,

* Belzona® 1111 ,

* Belzona® 9341,

* Belzona® 5811 ,

* Belzona® 6111 ,

* Belzona® 5111,

Problem

Due to the location of the tank it is subjected to a salt environment which accelerates corrosion externally as well as internal corrosion from the process chemicals.







Customer Location: North Sea gas producer

Application Date: 2003

Photograph Descriptions

- * Front view showing Belzona product,
- * Side view ,
- * Sealing of tank base seams using Belzona® 1111,

Application Situation

The open drains tank located below the platform handles the waste chemicals used in the platforms processes. Due to the location it would require extensive lifting facilities and mechanical work to replace.

Application Method

The tank base was grit blasted and plates were secured in position using Belzona® 1111 and held in place using chocks. Once the Belzona® 1111 had been allowed to cure, Belzona® 5811 was injected into the gap between the plate and the tank base. In addition all of the tank nozzles were wrapped using Belzona® 1111 / 9341 along with all of the tank base weld seams from the tank side/base joint. Following this the new tank base and sides were coated with Belzona® 6111 / 5111 for future corrosion protection.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

Belzona Facts The Belzona solution offered the customer a rapid turnaround as well a a cost saving in excess of \$200,000.