

BELZONA UPGRADES HOSPITAL ROOF

ID: 3866

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *New base layer Felt*
Products: ** Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Hospital, UK*
Application Date: *April 2011*

Problem

This hospital roof required an insulation upgrade and in addition, weatherproofing to prevent any further damage.



Photograph Descriptions

- * Insulation boards ready for installation on the deteriorated roof ,
- * First coat of Belzona® 3111 applied ,
- * Completed application ,

Application Situation

Large hospital roof which had deteriorated through weathering

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8. After installing insulation boards overlaid with felt, a fully reinforced Belzona® 3111 system was applied.

Belzona Facts

Since the application, the customer has saved on both heating and air conditioning costs and in addition, has reduced their carbon footprint.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve