

# BELZONA IS FOR ROOF PROBLEM AREAS

ID: 389

Industry: General Industry

Customer Location: Manufacturer of fine decorative metal art work in Santa Fe, New Mexico U.S.A.

Application: RPA-Roof Problem Areas


Application Date: December 2001

Substrate: Metal and built up roof

Products: \* Belzona® 3111 (Flexible Membrane) ,

## Problem

Heat, UV light, and pollution from the foundry below created water leaks on the roof mending joints, seams, standing water areas and flashings.



## Photograph Descriptions

- \* View of the roof. ,
- \* Flashing being sealed with the system. ,
- \* Vertical seams are sealed. ,

## Application Situation

Roof

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-6 and RPA-8.

## Belzona Facts

The Belzona System was used to seal all leaks. After several years there are no leaks and the system is in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

