

BELZONA IS FOR ROOF PROBLEM AREAS

ID: 389

Industry: General Industry

Customer Location: Manufacturer of fine decorative metal art work in Santa Fe, New Mexico U.S.A.

Application: RPA-Roof Problem Areas



Application Date: December 2001

Substrate: Metal and built up roof

Products: * Belzona® 3111 (Flexible Membrane),

Problem

Heat, UV light, and pollution from the foundry below created water leaks on the roof mending joints, seams, standing water areas and flashings.



Photograph Descriptions

- * View of the roof. ,
- * Flashing being sealed with the system. ,
- * Vertical seams are sealed. ,

Application Situation

Roof

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-6 and RPA-8.

Belzona Facts

The Belzona System was used to seal all leaks. After several years there are no leaks and the system is in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve