

# BELZONA REPAIRS FUELING HOSES

ID: 39


Industry: *Marine*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Ship bunkering (fueling) company, U.S.A.*  
Application Date: *March 1999*

Substrate: *Rubber*  
Products: *\* Belzona® 2211 (MP Hi-Build Elastomer) ,*  
*\* Belzona® 2911 (QD Conditioner) ,*

## Problem

*Bunkering hose outer skin damaged, potentially weakening the hose. A rupture could be catastrophic in terms of the environment and safety.*



## Photograph Descriptions

- \* Damaged section removed ,
- \* Damaged area after conditioning ,
- \* Applying Belzona® 2211 (MP Hi-Build Elastomer) ,
- \* Finished application is ready for service ,

## Application Situation

Bunkering (fueling) hoses

## Application Method

Application was carried out out in accordance with Belzona Know-How Leaflet SOS-12.

## Belzona Facts

Replacement cost of the hose section would have been \$5000. Belzona repair cost only \$200.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve