

BELZONA REPAIRS FUELING HOSES

ID: 39


Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Ship bunkering (fueling) company, U.S.A.*
Application Date: *March 1999*

Substrate: *Rubber*
Products: ** Belzona® 2211 (MP Hi-Build Elastomer) ,*
** Belzona® 2911 (QD Conditioner) ,*

Problem

Bunkering hose outer skin damaged, potentially weakening the hose. A rupture could be catastrophic in terms of the environment and safety.



Photograph Descriptions

- * Damaged section removed ,
- * Damaged area after conditioning ,
- * Applying Belzona® 2211 (MP Hi-Build Elastomer) ,
- * Finished application is ready for service ,

Application Situation

Bunkering (fueling) hoses

Application Method

Application was carried out out in accordance with Belzona Know-How Leaflet SOS-12.

Belzona Facts

Replacement cost of the hose section would have been \$5000. Belzona repair cost only \$200.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve