

Reconstrucción clásica de bomba con Belzona

ID: 3936

Industria: *Industria general*

Solicitud: *Bombas centrífugas*

Sustrato: *Acero*

Productos: ** Belzona® 1111 (Super Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,*

Ubicación del cliente: *Fabricante de cobre, Bélgica*

Fecha de aplicación: *Noviembre 2005*

Problem

El flujo de agua constante en la bomba produjo erosión/corrosión en partes críticas de la carcasa.



Descripciones de fotografías

- * Reconstrucción de perfiles ,
- * Otra vista de los perfiles ,
- * Aplicación finalizada ,

Situación de la aplicación

Carcasa de bomba

Método de aplicación

La aplicación se realizó de acuerdo con los folletos Belzona de Sistema Know-How CEP-1 y CEP-5.

Datos de Belzona

Belzona fue seleccionado porque el cliente había tenido numerosas experiencias positivas con productos Belzona en previas aplicaciones en bombas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Reparar • Proteger • Mejorar

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

