

DAMAGED FENDER REFURBISHED USING BELZONA® ELASTOMER

ID: 397

Industry: Oil & Gas

Customer Location: Offshore Oil Supply Ship Terminal,
Indonesia

Application: SOS-Ships and Offshore Structures

Application Date: 1991

Substrate: Rubber

Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,

Problem

Severe damage to the surface of fenders. In particular securing chains had damaged the rubber covers through constant abrasion.



Photograph Descriptions

- * Damaged rubber being removed. ,
- * Application of Belzona Conditioner. ,
- * Completed application. ,

Application Situation

Fenders used in docking of large ships.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SOS-12.

Belzona Facts

Due to their size the ability to make repairs on site quickly with Belzona Elastomers was a major benefit.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve