BELZONA UPGRADES SAFETY AND APPEARANCE OF SCHOOL ENTRANCE

ID: 3973

Industry: General Industry Customer Location: Secondary School, Port Talbort, South

Wales

Application: FPA-Floor Problem Areas Application Date: May 2012

Substrate: Concrete

Products: * Belzona® 4111 (Magma Quartz),

* Belzona® 5231 (SG Laminate) , * Belzona® 4411 (Granogrip) ,

Problem

Step nosings had become damaged and overall very dirty. The school wanted the main entrance upgrading and wanted to ensure the steps were safe for its staff, pupils and visitors.









Photograph Descriptions

- * Deteriorating steps at the entrance to the school ,
- * Repair to steps using Belzona® 4111,
- * Application of Belzona® 5231 overall,
- * Complete repair with Belzona® 4411 grip system applied to the step nosings. ,

Application Situation

Steps leading to school main entrance

Application Method

Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-8. The concrete step nosings were repaired using Belzona® 4111 before coating with Belzona® 5231. Finally a Belzona® 4411 grip system was applied to step nosings.

Belzona Facts

The application was completed by Belzona to a very high standard which was confirmed by the client. Not only has appearance been upgraded but the high visibility, non slip system on the step nosings provides improved safety by reducing risk of falls.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA