

SCHOOL BUILDING RESTORED WITH BELZONA

ID: 3974

Industry: Buildings & Structures

Application: WPA-Wall Problem Areas

Substrate: Bath Stone & Brick Fascia


Products: * Belzona 4141 (Magma Build) ,
* Belzona 5122 (Clear Cladding Concentrate) ,

Customer Location: Comprehensive School, South Wales

Application Date: February 2012

Problem

The stone work was weathering and the brick work was dirty. In addition there were areas suffering from rainwater ingress.



Photograph Descriptions

- * Front of the school with damaged areas of concrete ,
- * Damaged areas repaired with Belzona 4141 ,
- * Application of Belzona 5122 ,
- * Completed application ,

Application Situation

School building suffering for the effects of the weather

Application Method

Application was carried out in accordance with Belzona System Leaflets WPA-4 & 8. The Belzona 4141 was tinted with a cement tone additive to colour match the repair with the Bath Stone and to ensure a visually pleasing repair. The final stage of the application was to overcoat the surface with Belzona 5122.

Belzona Facts

Belzona completed the application to a high standard and the council responsible for the school was very pleased with the aesthetics of the repair application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve