

BELZONA SOLVES DREDGE PUMP WOES

ID: 40

Industry: Marine

Customer Location: Marine contractor, Panama City, Florida, U.S.A.

Application: CEP-Centrifugal Pumps

Application Date: August 1999

Substrate: Rubber

Products: * Belzona® 2311 (SR-Elastomer),

Problem

Large roots and stones damaged cutwater and stripped rubber coating from pump.



Photograph Descriptions

- * The damage ,
- * Completed repair ,
- * Dredge pump ready for service ,

Application Situation

Dredge pump repair.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet CEP-1.

Belzona Facts

Application proceeded rapidly using Belzona® 2311 (SR-Elastomer) to achieve full mechanical properties in less than two hours with minimal downtime for the dredge pump operator.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve