

# Belzona repairs damaged pre-heater fan shaft

ID: 4024

Industry: General Industry  
Application: MPT-Mechanical Power Transmission

Customer Location: Egypt  
Application Date: 2008

Substrate: Steel  
Products: \* Belzona 1111 (Super metal) ,

## Problem

The shaft was worn out under the bearing.



## Photograph Descriptions

- \* 1. The damaged equipment ,
- \* 2. The damaged area ,
- \* 3. The application before removal of formers ,
- \* 4. The completed application ,

## Application Situation

Worn shaft

## Application Method

This application was carried out in accordance with MPT-2. The shaft can be returned to its original dimensions by using released split formers. These can easily be removed once the product has cured to reveal a perfect finish.

## Belzona Facts

Conventional repair methods would be very time consuming and would be much more expensive. The Belzona solution however reduces this downtime to a fraction of the time and cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve