

Belzona repairs and protects rudder stock

ID: 4038

Industry: *Marine*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Egypt*
Application Date: *August 2007*

Substrate: *Carbon Steel*
Products: ** Belzona 1111 (Supermetal) ,*
** Belzona 1321 (Ceramic S-Metal) ,*

Problem

Ships rudder stock was suffering from the effects of erosion-corrosion



Photograph Descriptions

- * 1. Corrosion-erosion damage. ,
- * 2. Belzona 1111 successfully applied ,
- * 3. Belzona 1321 successfully applied ,
- * 4. Back in service after repair completion ,

Application Situation

Ships rudder stock needed rebuilt and protected

Application Method

This repair was carried out in accordance with MPT-1. The damaged area was rebuilt using Belzona 1111 (Supermetal) before the area was protected from further damage with Belzona 1321 (Ceramic S-Metal).

Belzona Facts

Belzona can successfully reverse the effects of corrosion-erosion damage by restoring machinery to its original dimensions. This can be achieved with minimal downtime and can be further protected by a Belzona corrosion resistant coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve