

# Belzona rebuilds damaged deck floor

ID: 4040

Industry: Chemical & Petrochemical

Application: FPA-Floor Problem Areas

Substrate: Mild Steel

Products: \* Belzona 1121 (Super XL-Metal) ,

Customer Location: Egypt

Application Date: 2007

## Problem

Severe pitting corrosion had occurred on the deck floor which needed rebuilding.



## Photograph Descriptions

- \* 1. Damaged Area ,
- \* 2. Surface Preparation ,
- \* 3. Belzona 1121 application ,
- \* 4. Completed application ,

## Application Situation

Corrosion occurring on deck floor

## Application Method

This was carried out using a modified version of FPA-1. After surface preparation the Belzona 1121 could be applied to restore the deck to its original dimensions.

## Belzona Facts

Belzona can return badly corroded areas back to their original dimensions and its has the capability to handle high compressive loads.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve