

Belzona provides internal corrosive resistant lining

ID: 4041

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon Steel
Products: * Belzona 5811 (Immersion Grade),

Customer Location: Egypt
Application Date: March 2006

Problem

Corrosion occurring on the internal surfaces which needed to be protected.



Photograph Descriptions

- * 1. Corrosion Damage ,
- * 2. 1st coat successfully applied ,
- * 3. 2nd coat application ,
- * 4. Completed application ,

Application Situation

Media filter requiring internal lining

Application Method

The repair was carried out in accordance with TCC-3. The two different coloured coats of Belzona 5811 were applied to avoid any pinholes or misses.

Belzona Facts

Belzona 5811 can be spray applied therefore larger applications can be completed quicker.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve