

Belzona SuperWrap en refinería

ID: 4094

Industria: Gas de petróleo
Solicitud: Válvulas, Tuberías y Accesorios
Sustrato: Acero
Productos: * Belzona® SuperWrap ,

Ubicación del cliente: Refinería, Francia
Fecha de aplicación: Marzo 2010

Problem

Se produjo corrosión en la sección de la tubería soterrada en la parte donde ésta emerge. La alta humedad a este nivel del suelo causó una severa corrosión en estas secciones expuestas de la tubería.



Descripciones de fotografías

- * Vista general de la refinería ,
- * Preparación ,
- * Aplicación en progreso ,
- * Reparación completada ,

Situación de la aplicación

Línea de alimentación de crudo en refinería

Método de aplicación

El Sistema Belzona SuperWrap fue instalado de acuerdo con los requerimientos ISO/TS 24817 y ASME PCC-2.

Datos de Belzona

Belzona SuperWrap se aplica con rapidez in situ y es una alternativa de fraguado en frío a la soldadura tradicional. Este sistema ha

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



sido extensamente utilizado para reparar y proteger tuberías similares en refinerías.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com

