

Belzona Rebuilds and Protects Pump Casing and Impeller

ID: 4192

Industry: *Fluid Flow*
Application: *CEP-Centrifugal Pumps*
Substrate: *Carbon Steel*
Products: ** Belzona 1311 (Ceramic R Metal) ,*
** Belzona 1321 (Ceramic S Metal) ,*

Customer Location: *Port Said, Egypt*
Application Date: *March 2007*

Problem

Pump casing and impeller had become damaged due to erosion-corrosion



Photograph Descriptions

- * 1. Original Damage ,
- * 2. Belzona 1311 completed application ,
- * 3. Belzona 1321 application ,
- * 4. Completed application ,

Application Situation

Pump casing and impeller

Application Method

Application was carried out in accordance with Belzona Know How System Leaflets CEP-1 and CEP-3.

Belzona Facts

Belzona 1321 provides excellent abrasion resistance and will completely eradicate the threat of corrosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2025


BELZONA®
Repair • Protect • Improve