

SOAP POWDER CAN'T WASH BELZONA AWAY!

ID: 420

Industry: *General Industry*

Customer Location: *Manufacturer of washing powder in Italy*

Application: *TCC-Tanks and Chemical Containment Areas*

Application Date: *On-going since 2002*

Substrate: *Cast Steel*

Products: ** Belzona® 4311 (Magma CR1) ,*

Problem

Corrosion from the soap powder and water mixture damages the housing and rotating elements of the mixer.



Photograph Descriptions

- * The mixer as it arrives ,
- * The coated rotating elements ,
- * The mixer end covers coated ,
- * The mixer body coated ,

Application Situation

Soap Mixer

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

Belzona Facts

The customer is pleased with the performance of the Belzona coating and there is an on-going program to protect these mixers.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve