

BELZONA REPAIRS PLATFORM'S SUMP PIPE

ID: 4271

Industry: Oil & Gas

Customer Location: Oil and Gas Platform, Rio Grande do Norte, Brazil

Application: VPF-Valves, Pipes and Fittings

Application Date: April 2008

Substrate: Carbon Steel

Products:
* Belzona 1111 (Super Metal) ,
* Belzona 1161 (Super UW-Metal) ,
* Belzona 5831 (ST-Barrier) ,

Problem

The sump pipe was cracked along its structure due to impact. It was required to seal the affected area using surface tolerant products that could also be used under water.



Photograph Descriptions

- * Adhesion test being carried out with plates coated with Belzona 5811 prior to application. ,
- * Testing Belzona 1161 on edges of plate under immersed conditions. ,
- * Application being carried out by divers under water. ,

Application Situation

Sump pipe at an oil and gas platform.

Application Method

Surface was cleaned in accordance with ISO 8501-1 St2/3 using a pneumatic sander. Fouling was chiseled away from the metallic structure. Prior to commencement of the application several plates were coated with Belzona 5811/Belzona 5831 to prevent and protect these pieces from further corrosion. Theoretical and practical training was imparted to the divers responsible for applying the products under water. Belzona 1111 was applied onto the panels before submersion. The plates were installed from top to bottom. "U" clamps were used to exert pressure onto the plates and to remove excess material. Belzona 1161 was then used to fill any gaps and to seal the ends of the plates. Upon completion, inspection was carried out and a small leak was detected. The leak was repaired with the Belzona 1161/Belzona 5831 system.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

This repair is in perfect condition up to date (2010).

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2025