

WET FLOORS MADE SAFE WITH BELZONA

ID: 440

Industry: *Buildings & Structures*

Customer Location: *Hospital - Victoria, British Columbia, Canada*

Application: *FPA-Floor Problem Areas*


Application Date: *March 2002*

Substrate: *Quarry tiles*

Products: ** Belzona® 1321 (Ceramic S-Metal) ,*

Problem

Slippery, wet floors



Photograph Descriptions

- * Preparation underway using special silicon carbide grinding tool and template ,
- * Masking completed and application of grip system in progress ,
- * View of completed section of food prep area ,
- * View of completed wash area ,

Application Situation

Non-slip safety system required on quarry tiled dish washroom and food preparation area floors which were constantly wet.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

Because the floors were constantly wet, there was always a threat that a serious accident could take place at any moment. A non-slip coating had been applied to other areas of the kitchen floor but this had proved to be ineffective over the long term. The coating had also started to loose adhesion in various places increasing the possibility of bacteria growth between it and the tiles beneath.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve