

# LEAKY ROOF IS NO PROBLEM FOR BELZONA


ID: 443

Industry: General Industry  
Application: RPA-Roof Problem Areas  
Substrate: Galvanized steel  
Products: \* Belzona® 3111 (Flexible Membrane) ,  
\* Belzona® 3921 (GSC Surface Conditioner) ,  
\* Belzona® 9311 (Reinforcing Membrane Sheets) ,

Customer Location: Factory roof - Texas U.S.A.  
Application Date: 2001 thru 2004

## Problem

Galvanized roof had numerous leaks around gutters. Previous attempts to stop leaks with conventional roofing materials failed.



## Photograph Descriptions

- \* Conditioned and coated ,
- \* Roof gutters ,
- \* View of roof area ,
- \* Another view of the gutters ,

## Application Situation

Sections of roof gutters

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

## Belzona Facts

Areas were cleaned, conditioned and two coats of Belzona® 3111 were brushed on. The total area protected with Belzona® 3111 was 8,000 sq. ft.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve