

# WATERPROOFING CHIME ANGLE WITH BELZONA

ID: 460

Industry: Power

Customer Location: Power Plant - Texas USA

Application: GSS-Gaskets, Seals and Shims

Application Date: May 2004

Substrate: Steel and concrete

Products: \* Belzona® 3111 (Flexible Membrane) ,  
\* Belzona® 3921 (PSC Surface Conditioner) ,  
\* Belzona® 9311 (Membrane Reinforcing Sheet) ,

## Problem

Corrosion was occurring on steel/concrete interface of wastewater tank and pad.



## Photograph Descriptions

- \* Close look at the problem area ,
- \* Prepared surface taped off ,
- \* Application completed ,

## Application Situation

Tank Chime Angle

## Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3.

## Belzona Facts

Customer had used Belzona® 3111 on many other water proofing repairs. Numerous attempts using caulking materials did not stand up to the requirements.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

