# WATERPROOFING CHIME ANGLE WITH BELZONA

ID: 460

Industry: Power Customer Location: Power Plant - Texas USA

Application: GSS-Gaskets, Seals and Shims Application Date: May 2004

Substrate: Steel and concrete

Products: \* Belzona® 3111 (Flexible Membrane),

\* Belzona $^{\circ}$  3921 (PSC Surface Conditioner) ,

\* Belzona® 9311 (Membrane Reinforcing Sheet),

#### **Problem**

Corrosion was occuring on steel/concrete interface of wastewater tank and pad.









# **Photograph Descriptions**

- \* Close look at the problem area,
- \* Prepared surface taped off,
- \* Application completed,

### **Application Situation**

Tank Chime Angle

## **Application Method**

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3.

#### **Belzona Facts**

Customer had used Belzona® 3111 on many other water proofing repairs. Numerous attempts using caulking materials did not stand up to the requirements.

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve