BELZONA REPAIRS WASTE WATER SLUDGE TANKS

ID: 4647

Industry: Water / Wastewater Customer Location: Sludge treatment site UK

Application: TCC-Tanks and Chemical Containment Application Date: May 2013

Areas

Substrate: Glass coated mild steel

Products: * Belzona® 1161(Super UW-Metal),

* Belzona® 5831(ST-Barrier),

Problem

All three tanks were suffering from through wall corrosion at the vapour interface level. The tanks could not be taken off line due to demand and any repairs would have to be carried out without hot works or the use mechanical equipment due to the risk of sparks.









Photograph Descriptions

- * Original tank condition. ,
- * Plate bonding be carried out with Belzona® 1161 from cherry picker no scaffolding was required. ,
- * Final coating with Belzona® 5831,
- * Area of finished repairs. ,

Application Situation

Sludge, Liquor and reception tanks fabricated from glass coated mild steel.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-3. After cleaning the areas surface preparation by hand abrasion was carried out. Repair plates pre-coated with Belzona® 5831 were cold plate bonded over the through wall defects using Belzona® 1161 finally Belzona® 5831 was applied to the entire repair areas.

Belzona Facts

The client had only been able to run the tanks at a reduced capacity of 65% causing increased transportation costs of sludge which

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



the site could no longer process. no other alternative were deemed to provide a viable solution to the customers requirements to keep the site running with minimal disruption and to be carried out without hot works or the use mechanical equipment due to the risk of sparks.