

# INSPECTION PIT SAFETY IMPROVED WITH BELZONA


ID: 466

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 5231 (SG Laminate) ,  
\* Belzona® 4411 (Granogrip) ,

Customer Location: Military installation - UK  
Application Date: July 2002

## Problem

Routine refurbishment of the workshops was being undertaken with particular emphasis on improving safety in and around the inspection pits.



## Photograph Descriptions

- \* Overview of the inspection pit, following application. ,
- \* Belzona systems improve safety on steps too. ,

## Application Situation

Workshop floors including inspection pit

## Application Method

After scabbling the concrete and planing rough areas a two-coat system of Belzona® 5231 was applied to the workshop floor and inspection pit. An additional strip of Belzona® 4411 grip system was applied to step nosings to provide additional grip and safety.

## Belzona Facts

A total of seven workshops have now been refurbished. The applications only took place after testing of the system to ensure it was

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

capable of performing well in the arduous workshop conditions where a variety of military vehicles up to four ton trucks are serviced.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

