

INSPECTION PIT SAFETY IMPROVED WITH BELZONA


ID: 466

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 5231 (SG Laminate) ,
* Belzona® 4411 (Granogrip) ,

Customer Location: Military installation - UK
Application Date: July 2002

Problem

Routine refurbishment of the workshops was being undertaken with particular emphasis on improving safety in and around the inspection pits.



Photograph Descriptions

- * Overview of the inspection pit, following application. ,
- * Belzona systems improve safety on steps too. ,

Application Situation

Workshop floors including inspection pit

Application Method

After scabbling the concrete and planing rough areas a two-coat system of Belzona® 5231 was applied to the workshop floor and inspection pit. An additional strip of Belzona® 4411 grip system was applied to step nosings to provide additional grip and safety.

Belzona Facts

A total of seven workshops have now been refurbished. The applications only took place after testing of the system to ensure it was

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

capable of performing well in the arduous workshop conditions where a variety of military vehicles up to four ton trucks are serviced.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

