

RUBBER TRACKS ON MOBILE DRILLING RIG QUICKLY REPAIRED WITH BELZONA

ID: 4683

Industry: General Industry
Application: SHM-Solids Handling Machinery

Customer Location: Geotechnical survey company, Croatia
Application Date: September, 2013.

Substrate: Rubber
Products: * Belzona 2311 (SR Elastomer) ,

Problem

Several damaged areas on its rubberized tracks required quick repair to prevent track failure.



Photograph Descriptions

- * Geo drilling machine on site ,
- * One of the damaged areas on the tracks ,
- * Damaged area after surface preparation and Conditioning ,
- * Application finished. ,

Application Situation

Mobile Geotechnical drilling machine operating two shifts per day.

Application Method

The application was carried out in accordance with Belzona System Leaflet SHM-1.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

The only alternative was to remove the machine from the building site to the workshop, which would cause downtime and delay to the operator. Belzona team did the repair within few hours' time and the machine was back in service the same day. Cost savings were significant in comparison to alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

