

# BELZONA ALLOWS HOUSTON CLARIFIER TO BE CLEAR AGAIN

ID: 4701

**Industry:** Water / Wastewater  
**Application:** TCC-Tanks and Chemical Containment Areas  
**Substrate:** Concrete  
**Products:** \* Belzona 4131 (Magma-Screed) ,  
\* Belzona 5811 (Immersion Grade) ,

**Customer Location:** Houston, TX, USA  
**Application Date:** September 2013

## Problem

*With damaged concrete and no coating, the trough was hard to keep clean, taking 2-3 times longer than when new.*



## Photograph Descriptions

- \* Overall view of clarifier ,
- \* After rebuilding with Belzona 4131 ,
- \* Completed project ,
- \* Completion application ,

## Application Situation

The customer was looking for a long-term repair in lieu of repairing it every 2-3 years as they have done in the past. With experience in other areas of the facility, the customer felt confident Belzona could do just that.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-9.

## Belzona Facts

The Belzona repair was able to be carried out over a long weekend at the facility in comparison to the competition taking them down for over a week, Belzona was chosen not only for the quick turn-around but also for a proven track record at the facility on other repairs. The facility saved time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve