

# BELZONA GIVES OLD PROPERTY NEW LEASE OF LIFE

ID: 4708

Industry: Buildings & Structures

Application: WPA-Wall Problem Areas

Substrate: Brick

Products: \* Belzona® 5151 (High Build Cladding) ,

Customer Location: Farm house, Worcestershire, UK

Application Date: June 2013

## Problem

Failure of the existing paint was allowing damp to penetrate into the walls leading to further deterioration. Client needed system to protect walls and approve appearance.



## Photograph Descriptions

- \* Surface Preparation ,
- \* Application of Belzona® 3911 (PSC Conditioner) ,
- \* Completed Belzona® 5151 Application. ,

## Application Situation

Old farm house walls.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1. A mechanical wire brush was used over the entire surface to remove loose material. After treating with fungicidal wash the Belzona® 5151 system was applied.

## Belzona Facts

Due to the contractor using Belzona products on a number of very successful applications within the social housing sector they were able to demonstrate the effectiveness of the Belzona® 5151 system to the client.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve