

# BELZONA SEALS LARGE BUND AREA

ID: 4714

Industry: Steel & Metal Processing

Application: TCC-Tanks and Chemical Containment Areas

Substrate: Brick

Products: \* Belzona 5811 (Immersion Grade) Belzona 4131 (Magma Screed),

Customer Location: Metals manufacturer, Herefordshire, UK

Application Date: November 2012

## Problem

The site is very keen on keeping up there high standards in health and safety and environmental issues and so regularly test for leaks .The bund was leaking in many areas through the brickwork.



## Photograph Descriptions

- \* Before application ,
- \* Creation of fillets at wall/floor joint with Belzona 4131 ,
- \* Application of first coat Belzona 5811 ,
- \* Completed application ,

## Application Situation

Chemical Bund on large manufacturing site

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-9 and TCC-15. The application took place during the planned two week shutdown and so no disruption to production.

## Belzona Facts

Belzona has been used on this site to provide solutions in a number of different areas. They now look to Belzona as "Problem Solving" and look to us to come up with alternative solutions to traditional repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve