

BELZONA REFURBISHMENT OF FLAT ROOF

ID: 4742

Industry:
Application: RPA-Roof Problem Areas
Substrate: Felt
Products: * Belzona 3111 (Flexible Membrane) ,

Customer Location: School, Grantham, UK
Application Date: 2013

Problem

The felt roof had deteriorated allowing numerous leaks into the areas below.



Photograph Descriptions

- * Section of roof before work started ,
- * Completed application ,
- * Upper section of roof before coating ,
- * Completed application ,

Application Situation

Large areas of flat roof over the sports and dining areas.

Application Method

Application was carried out in accordance with Belzona System Leaflets RPA-1, RPA-6 and RPA-8. After cleaning the roof and carrying out some localised repairs, a fully reinforced Belzona 3111 system was applied to the entire roof areas.

Belzona Facts

Client had already used Belzona on various roofing projects in the past and was happy with the system. The use of Belzona allows the roofs to be upgraded with minimal disruption.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

