

BELZONA SAFETY GRIP SYSTEM FOR ROOF ACCESS STAIRS

ID: 4887

Industry:

Application: FPA-Floor Problem Areas

Substrate: Terrazzo flooring



Products: * Belzona 4411 (Granogrip) ,
* Belzona 9211 (Super Grip Aggregate) ,

Customer Location: Markham, Ontario, Canada

Application Date: December 2013

Problem

Extensive water and salt exposure had made it virtually impossible to maintain the Health and Safety requirements for any extended period of time.



Photograph Descriptions

- * Stairs prior to application ,
- * Preparation complete ,
- * Application in progress ,
- * Complete application ,

Application Situation

Access to the roof via the smooth stairs.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Removed the existing adhesive tape and prepared the area ready for application. Belzona 4411 with Belzona 9211 was applied to eighteen steps and nosings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

The client was looking for a quick solution to be able to comply with Health and Safety requirements and selected Belzona as not only did it offer a quick repair but also provided a long-term solution. The application was completed within 5 hours and the client was able to reuse the stairs the next day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

