

BELZONA RESTORES JAPANESE ALUMINUM END COVERS

ID: 49

Industry: *Pulp & Paper*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Aluminum*
Products: ** Belzona® 1121 (Super XL Metal) ,*
** Belzona® 1321 (Ceramic S-Metal) ,*

Customer Location: *Paperboard Mill in Ontario, Canada*
Application Date: *September 1999*

Problem

Severe erosion caused by a combination of corrosive environment and abrasion of a fanbelt.



Photograph Descriptions

- * The corroded end cover. ,
- * Work in progress. ,
- * The end cover repaired and ready for service. ,

Application Situation

Aluminum end covers from formers of Kobayashi paper machine. Six formers with two end covers per machine.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet GSS-10.

Belzona Facts

Savings to the customer for six (6) pairs of formers exceeded \$60,000. The parts would come from Japan and so Belzona saved them 8 to 12 weeks' worth of downtime. The repaired parts should outlast new ones.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve