BELZONA USED IN MAJOR REFURBISHMENT OF 75-YEAR-OLD DAIRY

ID: 4970

Industry: Food & Drink

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona 4111 (Magma-Quartz),

* Belzona 4131 (Magma-Screed),

* Belzona 4141 (Magma-Build) ,

* Belzona 5231 (SG Laminate) ,

Problem

The dairy required several repair and maintenance solutions including localised repairs to the concrete floors, damage repairs to vertical columns, bonding on kerbstones and a non-slip, chemical resistant floor coating.







Customer Location: Dairy, Gloucestershire

Application Date: May 2013



Photograph Descriptions

- * Disused warehouse before application,
- * During application of Belzona 5231,
- * & 4. Completed application,

Application Situation

An old, disused warehouse needed to be transformed into a cold store as part of a major refurbishment of the family run dairy.

Application Method

Application was carried out in accordance with Belzona System Leaflets FPA-1, FPA-3, FPA-11 and WPA-4. A slurry mix of Belzona 4111 was used to bond on the kerbstones. Belzona 4131 was used to repair several areas of concrete floor damage. The floor and kerbstones were coated with Belzona 5231. Belzona 4141 was used to repair damage to the vertical concrete columns.

Belzona Facts

Backed by over 60 years of experience, Belzona were able to specify the appropriate materials and provide on-site training and guidance at every stage of the application.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA