

BELZONA SEALS GLAZING BARS

ID: 4972

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Aluminum and glass*
Products: ** Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Residential building, Croatia*
Application Date: *November 2013*

Problem

Water was penetrating the joints between aluminum frame and glass due to failure of the original sealant.



Photograph Descriptions

- * Damaged glazing section of the roof ,
- * Masking tape in place and Belzona 3921 conditioner applied ,
- * Application completed ,

Application Situation

Glazing section on the roof of the residential building

Application Method

Application was carried out in strict accordance with Belzona Know-How System Leaflet RPA-3.

Belzona Facts

Belzona was chosen by the owner of the building because the repair could be carried out quickly and with minimal disturbance for the tenants. It was a quick and cost effective repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve