

Standing Water - Not A Problem With Belzona

ID: 498

Industry: General Industry
Application: RPA-Roof Problem Areas
Substrate: Stainless Steel
Products: * Belzona® 3111 (Flexible Membrane) ,
* Belzona® 3921 (GSC Surface Conditioner) ,
* Belzona® 9311 (Membrane Reinforcing Sheet) ,

Customer Location: Air Force Base, Texas - USA
Application Date: March 2005

Problem

Leaking gutters



Photograph Descriptions

- * Gutters conditioned with Belzona® 3921 and seams coated with Belzona® 3111. ,
- * Seams coated with Belzona® 3111. ,
- * First coat of Belzona® 3111. ,
- * Second coat of Belzona® 3111. ,

Application Situation

Stainless steel gutters

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-7.

Belzona Facts

Gutters on roof were coated with "low bid" product. Subsequent leaks soon appeared. Client wanted a more durable solution and chose Belzona once again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve